

Schedule 67.1
Ontario Regulation 213/91 under the *Occupational Health and Safety Act*

Item	Offence	Section	Set Fine	Previous Set Fine
1.	Constructor failing to notify Ministry of Labour of construction project	6 (3)–(5)	\$550	New
2.	Constructor failing to notify Ministry of Labour of work on a trench	7	\$550	New
3.	Constructor failing to notify Ministry of Labour of use of suspended work platform system	7.1 (2) and (4)	\$550	New
4.	Constructor failing to appoint supervisor for project with five or more workers	14 (1)	\$550	New
5.	Constructor appointed supervisor failing to supervise work at all times	14 (2)	\$550	New
6.	Employer failing to appoint supervisor for five or more workers on project	15 (1)	\$550	New
7.	Employer appointed supervisor failing to supervise work at all times	15 (2)	\$550	New
8.	Constructor failing to establish written emergency procedures	17 (1)	\$550	New
9.	Constructor failing to post emergency procedures	17 (3)	\$550	New
10.	Worker failing to wear protective headwear	22	\$250	New
11.	Worker failing to wear protective footwear	23	\$250	New
12.	Worker failing to wear eye protection	24	\$250	New
13.	Employer failing to ensure training on fall protection	26.2 (1)	\$550	New

14.	Employer failing to ensure that written training and instruction record is prepared	26.2 (2)	\$550	New
15.	Employer failing to make training and instruction record available to inspector	26.2 (4)	\$550	New
16.	Constructor failing to ensure clean-up or toilet facilities available	29 (3) (a)	\$550	New
17.	Constructor failing to ensure required access to facilities	29 (4)-(7)	\$550	New
18.	Worker failing to use provided respiratory protective equipment	46 (2)	\$250	New
19.	Employer failing to develop written traffic protection plan for workers exposed to hazard from vehicular traffic	67 (4) and (5)	\$650	New
20.	Worker directing vehicular traffic for multiple lanes in the same direction	69 (2)	\$250	New
21.	Worker who may be endangered by vehicular traffic failing to wear prescribed garment	69.1	\$250	New
22.	Worker inappropriately standing or stepping on ladder	83 (2)	\$250	New
23.	Operator leaving controls of the machine unattended	102	\$250	New
24.	Worker passing shovel, backhoe or similar excavating machine or its load over a worker	103 (1)	\$250	New
25.	Worker passing crane or similar hoisting device's load over another worker	103 (2)	\$250	New

26.	Worker doing other work while acting as signaller	106 (1)	\$250	New
27.	Signaller failing to wear prescribed garment	106 (1.1)- (1.4)	\$250	New
28.	Worker using as a work place an object capable of moving supported by fork-lift truck, front-end loader or similar machine	107	\$250	New
29.	Worker failing to wear adequate personal protective equipment and clothing while using chain-saw	112 (1.2) (a)	\$250	New
30.	Worker failing to wear adequate eye and hearing protection while using chain-saw	112 (1.2) (b)	\$250	New
31.	Worker failing to wear adequate personal protective equipment while using fastening tool	117 (3) (a)	\$250	New
32.	Worker failing to wear adequate eye protection while using fastening tool	117 (3) (b)	\$250	New
33.	Employer failing to ensure that worker using suspended work platform system or boatswain's chair is trained	138 (1) and (2)	\$550	New
34.	Employer failing to ensure that competent worker is trained	138.1 (2) and (3)	\$550	New
35.	Owner failing to ensure there is an adequate roof plan	141.2 (1)	\$550	New
36.	Worker failing to wear full body harness connected to fall arrest system while on or getting on or off suspended work platform or boatswain's chair	142.06 (1)	\$350	New

37.	Constructor failing to notify Ministry of Labour of multi-point suspended work platform	142.3 (1)	\$550	New
38.	Worker without prescribed qualifications operating crane or similar hoisting device	150 (1)	\$250	New
39.	Worker without prescribed qualifications operating a crane or similar hoisting device	150 (2)	\$250	New
40.	Employer failing to ensure that qualified worker operates a rotary foundation drill rig	156.6 (1)	\$550	New
41.	Worker operating a rotary foundation drill rig without the prescribed training or qualifications	156.7	\$250	New
42.	Worker without prescribed qualifications connecting, maintaining or modifying electrical equipment or installations	182 (1)	\$250	New
43.	Constructor failing to establish and implement written measures and procedures	188 (4) (a) and 188 (5)	\$550	New
44.	Constructor failing to make written measures and procedures available to every employer on project	188 (4) (b)	\$550	New
45.	Employer failing to provide copy of written measures and procedures to a worker	188 (6)	\$550	New
46.	Employer failing to mark gas, electrical or other services before excavating	228 (1) (a)	\$650	New

47.	Employer failing to ensure that services are accurately located and marked before excavating	228 (1) (b)	\$550	New
48.	Worker failing to ensure that services are accurately located and marked before excavating	228 (1) (b)	\$250	New
49.	Constructor failing to take precautions to prevent damage to adjacent building or structure	229 (1)-(3)	\$550	New
50.	Worker operating machine so as to affect excavation wall stability	233 (3)	\$250	New
51.	Worker positioning machine so as to effect excavation wall stability	233 (3)	\$250	New
52.	Constructor failing to keep support system design drawings and specifications at project	236 (7)	\$550	New
53.	Employer failing to notify Director before working on tunnel, shaft, caisson or cofferdam	245 (1)	\$550	New